

Release notes 2.4

[Apr 21, 2017](#)

Contents Of Improved:

- (1) The system stability has improved.(the sticking notes)
- (2) Improved the problem that Contact delay parameter had effect on percussion release.
- (3) Improved the behavior when changing the glide range with glide on.

Updated Files:

- main1403.sys
- dsp0V1027.sys(no change file)
- dsp1V1027.sys(no change file)
- xk5_ini_setupV1028.sys(no change file)
- OscPreLoad1000.sys (no change file)

Latest Version:

- MAIN:V1.403
- WAVE INFO:V1.000
- DSP0:V1.027
- DSP1:V1.027
- FPATCH:V1.028